

SERVICE BULLETIN

DATE: September 2, 2009

BULLETIN NUMBER: 257

SUBJECT: Overspeed Board

Low Profile Gasoline Generators

MODELS AFFECTED:

5.0/4.2BCG, 5.0/4.2BCGA, 7.0/5.8BCGC and 7.0/5.8BCGD

DETAIL: Distributors, Dealers, Owners and Operators are advised that the above models have two Over Speed Boards depending on the Hertz operation of the unit.

60 Hertz (1800 RPM) models use Overspeed Board PN#046723

50 Hertz (1500 RPM) models use Overspeed Board PN#048801

When converting these models from one hertz rating to another the correct Over speed Board must be used. Failure to do so will result in either a premature shut down with no over speed occurring or a delayed shutdown when an overspeed occurs.

Place a copy of this bulletin in the Operators Manual pub# 46983 between pages 28 and 29.

